

Juli: Summary of Servicing, Repairs and Improvements From 2014

View on a laptop or PC

Click on the tabs at the bottom of the sheet to navigate around the spreadsheet
(If you're using an iMac and Apple software the tabs might appear at the top of the sheet.)



Click on the arrow to find additional pages

The information contained here has been obtained from the Juli Ships Log, Change Over sheets and old invoices going back to 2014. They aren't complete but do represent a decent effort to find relevant information.
They should be quite accurate from 2016.

IF this file has been sent to you as a PDF document ignore this page.
These directions relate to the spreadsheet version that is available on the Juli Ops Notes website.

Anchor, Chain, Windlass and Windlass Control

Date	Item	Description of maintenance	Supplier / Repairer	Cost
15/06/16	Windlass controller	Purchased by John after work week synicate decision to obtain a new one.	E.C. Smith & Sons, Luton	£68.77
09/08/18	Windlass	John: At Gouvia Marina: Windlass had stopped working. John attempted to fix it without success.		
13/08/18	Windlass controller	John: Electrician said a new remote controller was needed. It had been damaged by water ingress, probably by being left in the chain locker. New remote controller €85. Time: €40	Gouvia Marine	£111.61
01/12/19	Windless mounting plinth	Windlass was loose on its plinth, VYC made plates and rebolted it. €124	VYC / Nidri Marine	£112.50
01/03/19	Anchor	New Rocnor anchor purchased from Nidri Marine - €480 Recommended by VYC. 15% discount on gardiannage for having one.	VYC / Nidri Marine	£438.74
07/09/19	Windlass plinth	Windless loose on its platform. Temporary repair done. The timber, under the windlass, has snapped on two previous occasions in the last 5 years. We agreed to ask VYC to have a look at this.	Chris	
16/09/19	Windlass	Tom: The windlass was very sluggish. Caused by poor connections on HT leads and repaired them	Tom	
18/09/19	Windlass controller	Wouldn't retrieve. Sailing Holiday engineer moored nearby diagnosed a problem with the controller. Fortunately he had a spare one, which he gave to Tom. Tom gave him €20 for his time.	Tom + Sailing Holidays engineer.	£17.86
10/08/20	Added 10m of Chain	10m of anchor chain added. €70	VYC / Nidri Marine	£58.00
10/01/21	Windlass plinth	The windlass bacame loose again. VYC made a new shelf in wood and fibreglass. €820	VYC / Nidri Marine	£732.14
	Cockpit windlass control	Ftted by VYC after Ruairi showed Tom and John how handy it is for parking if you're short handed.	VYC	?
09/07/22	Windlass remote	Bought by Tom		£85.76
19/06/23	Windlass controller replacement	New controller box fitted by Ken from Maverick Marine. Tom found him. Ends to wires replaced although Ken had to return to a few days later to repair one that he'd missed.	Maverick Marine, Vliho	£182.45
04/07/23	Snubber & Chain Hook	To replace the existing ones that john lost whilst attempting to deal with a crossed anchor at Kalamos. €26, plus two x 4m lengths of rope for the snubber €11.20	Nidri Marinr	£32.53
23/08/23	Trip Hook	Purchased by Tom to replace the one John bought.	Coastline Technology	£32.24
25/08/23	Winlass Issue	Investigate windlass issue - separate motor from gearbox. €99.20 Inc VAT	VYC	£85.00
01/09/23	Windlass repair	Windlass motor repair undertaken by sub contractor involved by VYC €170 inc VAT	VYC	£144.00
01/09/23	Windlass repair	Refit the repaired windlass motor. 2hrs x €40 = €80 + €19.20 VAT = €99.20	VYC	£84.00
			Total:	£2,185.60

Batteries, Battery Chargers, Alternator and Solar Panels						
Battery Chargers						
Date	Battery Charger Type	Size (Ah)	Charger linked to..	Supplier	Guarantee	Cost
30/06/13	Battery charger. No mention of make or cost.					
02/02/14	2 x Ctek M100 @ £99.99					£199.98
26/06/16	Alan took both battery chargers home to test.					
17/01/18	New battery selector switch.. Alan					£36.36
22/09/19	Tom: Both battery chargers appear to have failed. Tom replaced them with a spare Sterling charger set to charge both leisure batteries. It works ok but a little noisy.					
19/08/20	2 x CTEK CTA-M100 7A 12V Marine 8-Stage Battery Chargers. 2 x £115.25	7A	One for each leisure battery	Amazon (The Perfect Signal Ltd.)	5 Years	£230.50
14/02/22	Battery Monitor. £220.93. Cost for fitting not known.			VYC supplied it.		£220.93
					Total:	£687.77

Batteries.							
(Please label new batteries with their designated number/role and date purchased)							
Date	Nature of issue	Spec	Battery Number/Role	SupplierF14:F25	Guarantee	Fitted by	Cost
01/01/14	Lucas LM26MF. purchased by Alan?	100Ah	?				£67.99
11/06/16	Platinum 110L brought out on Work Week	110Ah	1.2	Alpha Batteries	3 Years		£94.99
26/07/16	Battery - John	100Ah	1.1	Franks, Corfu			£117.29
18/06/18	No2 Battery replacement Tom? €130	70Ah	No.2	Franks, Corfu			£114.58
08/10/19	Battery - Chris	100Ah	1.2	Nydri Marine			£114.04
09/08/21	2 x Domestic batteries. Varta £140 each	100Ah	Dom 1 and Dom 2	Nydri Marine	?		£280.00
30/08/21	1 x Engine battery. Varta. £140	100Ah	Engine	Nydri Marine	?		£140.00
09/11/21	2 x battery switches €20.			Nydri Marine		VYC	17.38
28/11/22	Additional leisure battery	100aAh	Dom 3		?	VYC	£169.08
	On 11/23 Invoice. Red Battery cable 35mm			? VYC		VYC	
01/05/23	4 batteries secured. 2 with a strp, 2 others wedged in place.					Chris	

						Total:	£1,115.35
--	--	--	--	--	--	---------------	-----------

Alternator:					
Motorola 9AR 2958P (70AMP) Belt Types: (Perkins 264B536Y. Perkins Part is: P2614B636 Other belt info: 4Q9O344) https://www.startermotor-alternator-store.co.uk/12v-160amp-high-output-marine-alternator-11189-p.asp					
Date	Remarks	Engine Hours	Supplier/Repairer	Is there a spare on board	Cost:
14/06/21	The belt delaminated and came off the pullies. This occurred just outside L Vathi during John's holiday. There was a spare belt available onboard.	?	Ruairi (VYC) fitted the spare. Although unused, the spare was very old.	?	
01/05/22	New belt fitted as part of the engine service by Theo				

Solar Panels				
Date	Remarks, Type, Measurements	Other comments	Repaired / Supplied by	Cost
17/03/16	150w semi flexible solar panel and controller	Purchased by Tom. during work week.	Photec Univers	£469.99
30/07/20	Solar panel connectors	Purchased by Tom.	Photec Univers	
14/02/22	Measurements taken for the new solar gantry. €25 + €6 VAT	Measured by VYC	VYC	£27.07
28/11/22	MPPT Controller		VYC	
25/04/22	Gantry for panels. €425 for 50% deposit paid.		Philip Thomas	£371.18
	2 x 175w panels Victron SPM041751200 1485 x 668 x 30mm, weight 11Kg ??		VYC	£353.00
	2 x NOA sets of brackets to attach panels to the gantry. €107 each inc VAT. €214		VYC	£189.00
	Labour cost for installing solar panels		VYC	£264.00
	Victron connectors. €33.87 + €8.13 VAT = €47	From VYC 24/11/23 invoice	VYC	£40.86
01/05/23	Replaced new connector to the solar panels.		Chris	

			Total:	£1,715.10

Boat Yard Fees

Year	Yard	From	To	€ Cost €	VAT	€ Total €	£ Rate £	£ Total Cost £
08/11/23	Yard decommission: lower and flake chain, connect to shore power, clean props, shafts and wash anchor chain. 2hrs @ €35			€ 70.00	€ 16.80	€ 86.80	£1.16	£74.83
18/10/23	Take to the yard and lift. 1Hr @ €35 + €8.40 VAT			€ 35.00	€ 8.40	€ 43.40	£1.16	£37.41
2023	Nidri/VYC Yard Fees - winter package.					€ 0.00		£1,669.42
2022	Nidri/VYC Yard Fees - winter package.	?/10/2021	?/4/22	€ 1,500.00	€ 360.00	€ 1,860.00	£1.15	£1,624.45
2021	Nidri/VYC Yard Fees - winter package.	01/10/20	01/06/21	€ 1,736.00		€ 1,736.00	£1.15	£1,516.16
11/08/20	Nidri/VYC Yard Fees - winter package.	09/10/19	27/07/20			€ 2,046.00		£1,851.63
2020	Take to yard and haul. Drop anchor and connect to shore power					€ 74.40	£1.15	£64.98
16/05/19	Nidri/VYC Yard Fees - winter package.					€ 1,500.00	£1.13	£1,328.61
24/05/19	Fit new anchor, prep boat and launch							£67.02
07/12/18	VYC. Take boat to yard and lift, drop anchor and flake chain. Disconnect batteries, clean prop, check and grease seacocks. Remove unnecessary fuel pipes.					€ 0.00		£245.68
18/08/17	Marina Fees. Lift out and pressure wash. Gouvia					€ 0.00		£3,533.73
25/09/17	Marina Fees. Gouvia					€ 0.00		£532.54
20/08/16	Marina Fees. Gouvia					€ 0.00		£779.15
28/09/16	Marina Fees. Gouvia					€ 0.00		£3,161.50
2014	Lift back in. Gouvia					€ 0.00		£173.57
2014	Marina Fees. Gouvia					€ 0.00		£3,091.00
2014	Lift to hard standing, Gouvia					€ 0.00		£327.00
						€ 0.00		

Electrics: Wiring, lights, switches etc.

Date	Notes	Supplier	Repairer / Purchaser	Cost
09/11/21	Investigate engine not starting. After testing replaced negative from battery to engine. Charging then found to be low so replaced charging wires. Labour: 4hrs €148.80	VYC	VYC	£129.27
09/11/21	Fabricate new switchboard. Replace wiring , several wires found to be burnt. Refit all parts and test. Labour: 16hrs. €595. 1 x switchboard €110. 2 x battery switches. €20.	VYC	VYC	£630.00
14/02/22	New switch(?) started sorting old cables(?) found and fixed issue with charger wires. Fitted battery monitor. (Battery Monitor cost €204) Labour: 16hrs €595	VYC	VYC	£1,100.00
14/02/22	The above charge included cleaning a breather and repairing the hatch frame.		Hard to calculated costs for each job.	
14/02/22	Sort out shore power (Labour cost also includes a charge for remove 3 damaged stantion based and servicing winches.)			
28/11/22	Replace masthead/steaming light	VYC		£298.83
01/05/23	Auto pilot now working after a loose wire found inside the controller. The bracket(?) was also adjusted and it now runs more smoothly. It worked effectively on a broad reach!			
			Total:	£2,158.10

Engine, Throttle, Gearbox, Propshaft and Propeller				
Date	Notes	Supplier	Repairer / Purchaser	Cost
09/03/16	Sound insulation	Alan	Alan	£185.22
07/06/16	Reverse gear repair	David Nash	John	£155.00
12/07/16	Fuel pump repair kit £37.95. Repair of fuel pump €500. New alternator belt adjustment bracket. €50	Alan	Alan	£37.95
12/07/16	Fuel pump repair by engineer, plus €50 for alternator adjustment bracket €500 (Rate 1.24)		Alan	£443.55
19/06/17	Recon engine, engine mounts, delivery	Parts4Engines	John	£2,796.00
20/06/17	Oil pump for new engine	Parts4Engines	John	£192.00
08/09/17	Part of payment for fitting the new engine	David Nash	John	£1,508.41
12/10/17	Engine service	David Nash	John	£210.00
17/01/18	Replaced Oil Pressure and Temperature Gauges		Alan	£100.00
08/01/18	Battery selector switch		Alan	£36.36
13/08/18	Engine failure in Vliho Bay. Engine rebuild required. €1,500 as part payment for parts for engine rebuild.	John to Vliho YC. Part Payment	Fotheri/Dad	£1,372.50
12/09/18	Part payment engine. €300 for fuel pump + €1500 for engine rebuild. (€1800 @ 1.099)	Chris to Vliho YC. Final balance	Fotheri/Dad	£1,638.30
19/09/18	Tom and John went out to check on progress and put the boat to bed. The engine rebuild was complete and ready for testing. The engine had to be run-in for 30 hours. It had been repaired by Fotheri and his father, from Nidri, who had been brought in to do this by VYC.		VYC/Fotheri&dad	£0.00
26/09/18	The engine ran well and sounded really good. There was a persistant fault with air getting into the fuel lines which caused problems starting the engine. We decided to leave Juli at VYC over the winter so they could deal with this and do some other jobs that were required.		VYC/Fotheri&dad	£0.00
05/11/18	Cost of new clutch during engine rebuild	Vliho YC	VYC/Fotheri&dad	£240.00
01/12/18	Repair oil pressure alarm and wiring in engine bay. Purge air from fuel line at the time of the rebuild.	Vliho YC	VYC	£73.09
07/01/19	Repair and reconnect oil pressure alarm. Part of a bill including other items. €80.40	Vliho YC	VYC	

Engine hours use, plus oil/filer changes and fuel filter changes since the engine rebuild in 2018 and Gearbox oil changes.				
Engine hours use each year				
Year	Engine Hours: Start of Year	Engine Hours: End of Year	Yearly Engine Hours Total	Remarks
2018	From Engine rebuild (19/9/18): 1343	1370	27	Record began after the engine rebuild
2019	1370	1562	222	
2020	1601	1691	90	Disrupted by Covid pandemic
2021	1691	1852	161	
2022	Info missing. Ships log lost in post	2024	172	
2023	2024	2205	181	
2024	2205			
2025				
Total Engine Hours:			853	

Engine oil and filter changes since July/Aug 2018.					
(Change oil and filter every 150 hours. Best oil is 15/40 Diesel Turbo.)					
Filter Types: (Current type 24/9/21) MAHLE OC33. Others mentioned in the Ops Notes: P2654403, Wix 51806 or Fram PH2821A					
Date	Remarks	Engine Hours at Oil Change	Hours between oil change	Who carried it out?	Spare oil filter on board?
19/09/18	Rebuilt engine, oil and filter change	1343		Fotheri (Engineer)	Yes
24/05/19	30hrs oil change and head retorqued	1370	27	Fotheri's dad	Yes
22/09/19	150hrs change	1544	176	Tom	Yes
09/06/21	150hrs change + new flexi pipe from the stirrup pump to assist gathering old engine oil as its pumped out.	1691	152	John/Fotherie's dad	Yes
09/05/22	Engine hours checked by Chris - first one out.	1844	144	VYC	
05/05/23	Engine hours checked by Chris - first one out.	2029	185	Chris	?
10/09/23	Chris carried this out. No oil filter change	2150	121	Chris	No

--	--	--	--	--	--

Fuel filter changes since August 2018						
Filter Types: Current one (24/9/21) Coopers FIAAM FT4788).						
Spare: a Crossland 522. Many alternatives. Online recommendations suggest to change filter annually.						
Date	Comment	Engine Hours - New	Engine Hours - Change	Hours Used	Supplier/ Repairer	Spare filter on board?
01/08/18	New fuel filter and filter housing fitted during engine rebuild.	1343			VYC	Yes. 1 x Crossland 522
28/11/22	Fuel filter change as part of a large engine service.				VYC	

Gearbox oil changes						
Oil: Automatic Transmission Fluid (ATF) 1Ltr						
Date	Comment	Engine Hours - New	Engine Hours - Change	Hours Used	Supplier/ Repairer	Spare filter on board?
01/08/18	No Record of oil changes occurring before					

Hull Related: Gel Coat, Antifouling, Rudder, Steering, Auto Helm, Safety Rails, Hatches, Seacocks, Fenders, Bimini, Sprayhood, Internal and External Lighting etc

Date	Item Description	Supplier	Purchased By	Total €	Exch Rate	£ Amount £
2015	Coppershield 2000 6kg and (3kg kit in 2014)					£233.88
2015	Hatch cover	Lewmar				£465.36
06/04/17	Coppershield 2000 3kg kit	CFS Fiberglass	John			£99.13
17/04/18	Antifouling pack	Franks, Gouvia	John			£63.00
26/02/18	New Bimini and sprayhood	Ritchie, Stockton	John			£340.00
07/12/18	Rebuild a new rudder as it had become delaminated. €1,439	VYC	Syndicate			£1,284.00
08/05/18	2x ball fenders and socks. Tin of prop paint.	Franks, Gouvia	John			£161.30
17/05/18	Flexible water tank 75ltr	Force4 Chandlery	Chris			£53.49
24/05/19	Antifowling	VYC	John			£242.16
24/05/19	Fit new Anodes	Vliho YC (See Invoice)	John			£41.22
24/05/19	New 15kg Rocna anchor	VYC	John	€ 487.00		£438.74
24/12/19	Wind speed and direction indicator	Ebay	Chris			£214.95
18/06/20	Phifertex plus polyester webbing for new window coverings	Kayospruce Ltd	Tom			£170.81
18/06/20	Clear acrylic sheet for new windows.	Plastic Sheet Shop Ltd	Tom			£167.70
13/07/20	New window coverings. £90. Repair to one window cover + 3 keys	?	Tom			£123.10
13/07/20	Step nosings, paint, outboard cover, rubber trim for CP Locker	Various online	John			£98.59
30/07/20	2 x 12v Deck plugs and sockets	TCS Chandlery	Tom			£27.85
11/08/20	Reseal saloon hatch	Vliho YC (See Invoice)				
15/07/21	Ball fender covers, water filter €84	Nydri Marine	Tom			£73.68
14/02/22	Refurbishmet of safety rails/stanchions. 2x upright bases @€39 each. Cost of fitting unknown.	VYC	Syndicate	?	£1.15	?
14/02/22	Service winches - very poor condition.	VYC	Syndicate			£300.00
01/05/23	Fitted new port and starboard saloon windows. Chris and Co. Windows purchased and sent out to VYC by Tom. See 18/6/20	Tom	Tom			
12/05/23	Long plank missing. Vicky about she found us a good replacement.	Tom got one off Vicky				

02/06/23	New antifouling	VYC			£2,063.00
02/06/23	2 Anodes - 1 prop and 1 round	VYC			£22.00
01/05/23	Fitted second jubilee clips to seacocks which needed them.		Chris		
			Total:		£5,984.72

Boat Insurance

Year	Company	Premium	From	To	Excess
2025					
2024					
2023	Towergate Insurance	£391.22	10/05/23	09/05/24	£250.00
2022	Towergate Insurance	£286.10	10/05/22	09/05/23	£250.00
2021	Towergate Insurance	£264.01	10/05/21	09/05/22	£250.00
2020	Towergate Insurance	£219.30	10/05/20	09/05/21	£250.00
2019	Towergate Insurance	£270.23	10/05/19	09/05/20	£250.00
2018	Towergate Insurance	£253.94	10/05/18	09/05/19	£250.00
2017	Towergate Insurance	£314.13	10/05/17	09/05/18	£250.00
2016	Towergate Insurance	£281.92	10/05/16	09/05/17	£250.00
2015	Towergate Insurance	?	10/05/15	09/05/16	£250.00
2014	Towergate Insurance	£273.83	10/05/14	09/05/15	£250.00
2013					
2012					
2011					

Outboard Motor and Dinghy

Date	Item Description	Supplier	Purchased By	Amount
12/09/18	Carburettor for outboard	Chandlery in Morpeth	John	£115.74
31/01/19	Repair to outboard in 2017/8	David N. Gouvia	John	£100.00
12/03/19	Outboard bracket moulding.	Polymarine Ltd, Colwyn Bay	Tom	£23.46
24/05/19	Outboard repair	VYC	John	£123.89
03/05/19	Boat kill switch	Amazon	John	£8.17
09/11/21	Outboard service €90	VYC	John	£78.19
14/06/23	Second hand Honda outboard. €325. Old one beyond economic repair.	?	Tom	£282.36
24/07/23	New Arimar Tender Softline 240cm x 153cm	Maverick Marine	Tom	£496.69
			Total:	£1,228.50

Plumbing: Heads, WC, Galley, Fridge, Stern Shower, Water Tanks

Date	Notes	Purchased from	Repairer	Cost
2015	Toilet seat			£80.00
29/02/16	Various toilet fittings	TCS Chandlery	Tom	£36.43
04/03/16	Toilet non-return valve	Vetus	Tom	£36.91
09/05/18	Galley sink tap	Profi, Corfu	John	£40.43
14/05/18	Replace stern shower	Mailspeed Marine	Tom	£62.43
17/05/18	Replace flexible water tank 75ltr	Force4Chandlery	Chris	£53.95
02/06/18	New 75Ltr flexible freshwater tank fitted as the old one was leaking.	Force4 Chandlery	Chris	£53.95
20/06/18	Toilet stopped working. Mains feed connector block corroded. Replaced and made new ends.		Tom	
30/07/18	Tom: Fridge not holding temperature			
01/08/18	John: New fridge from UK.. £833.95. Couriour Mr McJ on 13/8/21. £980 including courier fees.	Jackson's Leisure Supplies	John	£980.00
24/05/19	Fit new connection to hot water tank. (1 hour labour) €24.80	VYC	VYC	£22.34
09/11/21	Change 1 way valve on toilet	VYC	VYC	£37.20
27/01/20	Pressure release valve for the hot water tank.	Advanced Water Co	Tom	£26.74
22/03/21	New holding tank €802.26	Fabricated by VYC	VYC	703.74
01/04/21	Replacement freezer door delivered. Provided within the guarantee. (Still to be fitted.)	Jackson's Leisure Supplies		£0.00
10/05/21	New Toilet non-return valve	Vetus	VYC	£52.55
09/11/21	1 x Jabsco 3 way flush switch. €43.50. 1 x non return valve. €11. Labour: €30	VYC	VYC	£72.54
23/07/23	Fix electric toilet flow - 1 1/2hrs @ €40 = €60 + €14.40 VAT	VYC	VYC	£74.40
07/08/23	3.5 Bar pressure relief valve	Advanced Water Co	Tom	35.28
24/07/23	Toilet non return valve €22.40	JFK Marine Supplies	Tom	£19.46
26/07/23	Toilet non return valve €35.00	Nydri Marine	Tom	£30.41
06/09/23	Pressure release valve fitted to the calorifier. Had trouble getting the fitting to seal on the pipe.		Chris	
?/9/23	Shower drain pump switch not working. New one purchased. Needs to be fitted.	Bob Purchased a new one.	Bob	
	Fitted an extra non-return valve to the outlet from the toilet. It doesn't flow back into the bowl so quickly now.		Chris	

			Total:	£2,418.76

Steering, Rudder and Auto Helm, etc

Date	Notes	Repairer	Price
2015	The auto helm belt slips, particularly in heavy weather. This has been an ongoing problem for many years - since 2014 at least. There are spare belts on board but they too are very old. Perhaps we should invest in a new one.	?	
30/07/18	Remounted the wooden block that supports the autohelm. Removed nuts from the bolts underside in engine bay and replace with nylox nuts.	Tom	£0.00
07/01/19	Repair to rudder	VYC	£1,424.12
22/03/21	Investigate steering issue. The wheel feels very tight. System serviced and greased. (€ not easy to calculate from VYC bill.)	VYC	?
03/04/22	Repair to rudder caused during John giving assistance to Sailing Holidays at Hotel Iris. Sailing Holidays paid for the repair.		
		Total:	£1,424.12

Sundry Items

Date	Item Description	Supplier	Purchased By	Amount
11/05/16	New SSR registration £25 to add John's name	M&C Agency	John	£25.00
02/06/16	4 pillows @ €4.95. 2 double quilts @ €18.95. 1 single quilt @15.45.	Profi, Korfu	John	£63.88
06/04/17	Bosch drill with two batteries	B&Q Middlesbrough	John	£90.00
08/07/18	Replace galley sink	Profi	Tom	£16.36
26/02/18	New Bimini and Sprayhood	Richie, Stockton on Tees	John	£340.00
14/05/18	Surveyor Fees	Geoff Pollock. Gouvia	John	£450.00
17/06/18	Hozelock connector and nozzle	Homebase, Bishop Auckland	John	£10.40
24/05/19	Fit new Anodes	Vliho YC (See Invoice)	John	£41.22
20/03/19	Yachtshare finder - adverts	Paypal	Tom	£51.00
20/03/19	Gumtree adverts	Paypal	Tom	£11.98
09/07/19	Hose connector, hose spray gun,	Nidri Marine	Tom	£12.00
03/02/20	New SSR to include Geoff	M&C Agency	John	£35.00
19/03/20	Repair to saloon table - replace gas strut	VYC		£160.00
24/05/22	Mattress topper for fwd berth	Ship Shape World	Tom	£132.75
09/07/22	2 x 12v Clip on fans - rechargeable	Amazon	Tom	£50.00
09/07/22	Dual fast charger socket. 4.8A USB		Tom	£11.98
02/06/23	Survey Fee: Out of the water survey for the insurance company	VYC		£753.93
17/07/23	New SSR registration to include Bob and Roger. £35 + £6.85 registered post	M&CA	John	£41.98
01/05/23	12v Hoover now working.		Chris	
	F			
			Total:	£2,297.48